
Property Repairs


May 10 2012



Disturbed/compacted soil by drilling equipment near well head




Disturbed area looking west




Disturbed area looking north




Additional topsoil



Topsoil after grading



Trenches added



Broad view of trenches